




# RIVER MILE 10.9 REMOVAL ACTION WATER QUALITY MONITORING PROGRAM WEEKLY REPORT

## Summary of water quality monitoring for the week ending July 20, 2013

Dredging operations, which began on August 2, 2013, are being continuously monitored to ensure that water quality is maintained at acceptable levels within the River. To monitor water quality, a number of sampling locations have been established shown on the map below.


*For the week ending of July 20, 2013 operations were conducted within acceptable water quality limits.*


*NOTE: this is where text will provided if exceedances occur and mitigations measures*



## Water Quality Monitoring Data

Buoy #	Turbidity (NTU)	
	1-Hour Rolling Average for the Week	Std Deviation
1	12.1	10.9
2	17.7	27.5
3	16.8	39.2
4	8.1	4.2





### Water Quality Monitoring Locations

NOTE: Temporary figure - working on a revised one just for weekly report.